

Part No.: ML2A

Motor Model: C01

Serial No: 01 Test

Tested By: GRV

Test Date: 2026-06-24

INSPECTION CHECKLIST

S.NO	DESCRIPTION	SPECIFICATION	METHOD OF CHECK	OBSERVED	STATUS
1	Spigot Seat	154.90 (0.00/-0.03) mm	OD Snap gauge	—	—
2	Front Mounting Thread	3x M6×1 - 6H, depth 18.00 mm	Plug gauge check found OK	—	—
3	Shaft OD Total Runout Wrt Datum B	0.1 mm	Total Indicator Reading	—	—
4	Shaft Front Face to Front Mount Spigot Seating Distance	28.20 ± 0.50 mm	Height Gauge	—	—
5	Shaft Spline	As per Drawing	Master Spline	—	—
6	Dry Leak Test	at Min. 0.2 bar	Pressurised air and foam water	—	—
7	Thermister Fuction	Resistance at room temperature	Resistance meter	—	—
8	Sensor Cable Color Sequence	Pin 1 - Red (Vdd (+5V))	Visual	—	—
9	Sensor Cable Color Sequence	Pin 2 - White (PT 1000 +ve)	Visual	—	—
10	Sensor Cable Color Sequence	Pin 3 - Yellow (Sin output)	Visual	—	—
11	Sensor Cable Color Sequence	Pin 4 - Blue (Cos output)	Visual	—	—
12	Sensor Cable Color Sequence	Pin 5 - Black (Common GND)	Visual	—	—
13	Sensor Cable Color Sequence	Pin 6 - Green (Shield + Wire)	Visual	—	—
14	Motor Length	177.8 (+/- 1.5)	Height Gauge	—	—
15	Motor Weight	12.1 (+/- 0.15)	Weight Scale	—	—
16	Phase Cable Grommet	Manual Assembly	Visual	—	—
17	Terminal Cover	Manual Assembly	Visual	—	—
18	Terminal Cover Assembly Bolts	Manual Assembly	Visual	—	—
19	Phase Cable Assembly Bolts	Manual Assembly	Visual	—	—
20	Visual Defects	Free From Rust, Dust, Physical Damage, Loose fitments, Missing Components	Visual	—	—
21	Deviations if any	—			

ⓘ This is a system-approved document; signatures are not required.

INSPECTION RESULT: **FAILED**

INSPECTED BY: GRV INSPECTION DATE: 2026-06-24