

WMATA SCI IDENTIFIED ITEMS (4/28/2021)

Item Number	Description	Area/ Segment or Building	Specific Location	Technical Requirements	Discipline	Originator	Remarks	Photos
1	sealant at base of wall	WHB	EXTERIOR SOUTH/EAST		ARCH	AA	repair sealant not adhering	WHB_AA_01
2	door opening	WHB	EXTERIOR SOUTH/EAST		ARCH	AA	fix chipped wall edges	WHB_AA_02
3	door opening	WHB	EXTERIOR SOUTH/EAST		ARCH	AA	patch hole at door entrance	WHB_AA_03
4	expansion joint at upper wall panel	WHB	EXTERIOR SOUTH/EAST		ARCH	AA	remove gray markings at expansion joint	WHB_AA_04
5	metal coping	WHB	EXTERIOR SOUTH/EAST		ARCH	AA	clean-up exposed piece of roofing membrane. Align metal coping at corner. Check and repair source of water stain on wall panel.	WHB_AA_05
6	concrete floor	WHB	MEZZANINE		ARCH	AA	patch chipped and floor voids	WHB_AA_06a WHB_AA_06b
7	exit doors	WHB	INTERIOR EAST		ARCH	AA	panic hardware needs to be provided for all emergency exits.	WHB_AA_07
8	lighting	WHB	INTERIOR EAST		ARCH	AA	replace orange lightbulbs	WHB_AA_08a WHB_AA_08b
9	breakroom furniture	WHB	OFFICE AREAS		ARCH	AA	furniture missing	WHB_AA_09
10	receiving office furniture	WHB	OFFICE AREAS		ARCH	AA	(1) wardrobe for WS-3 station appears to be incorrect (all wardrobe shelving should face the worksurfaces). WS-1 station does not match the design, please check the size of the worksurface return). File cabinet doors needs to be adjusted. Some furniture in room are missing.	WHB_AA_10a WHB_AA_10b WHB_AA_10c
11	control office furniture	WHB	OFFICE AREAS		ARCH	AA	a couple of furniture partitions are missing. File cabinet doors needs to be adjusted. Some furniture in room are missing.	WHB_AA_11a WHB_AA_11b
12	door	WHB	EXTERIOR NORTH/WEST		ARCH	AA	door cylinder lock is broken	WHB_AA_12