



RIDHIRA ZEN

Project Site Progress Update 1st April to 31st April






backfilling near M1 road













CR-10 road wmm completed





CR12 road water curing





CRS Wall near Villa no 22 to 26





Phase 2 CC Road casting





Plastering in villa 32





Road compaction





Villa no 23 landscaping







Villa no.32 first floor wall plastering work in progress





Villa no.78 plinth beam shuttring work





Villa no.79 footing casting work





Villa no.83 plinth beam reainforcement work