#### **Heritage Sites Health Monitoring**

# **Analysis Report**

Image: Tajmahal-veg.jpeg

Date: 2025-06-02 19:00:03

#### **Original Image**



### **Heritage Sites Health Monitoring**

# **Biological Growth Detection**



#### **Heritage Sites Health Monitoring**

## **Analysis Summary**

Material Detected: Plaster

CO2 Savings: 0.04 kg

Water Savings: 0.43 liters

Biological Growth Area: 43.33 cm<sup>2</sup>

Predicted Future Severity: No cracks detected for prediction

Recommendation: Use biodegradable cleaners.

ID	Туре	Width (cm)	Length (cm)	Severity	Confidence
Vegetation_1	Vegetation	13.20	7.30	N/A	0.77