

Incident Overview

Field	Value
Severity	MODERATE
Vehicles	sedan, pickup truck, motorcycle
Road	dry asphalt
Weather	clear
Visibility	good
VLM Model	minicpm-v
Inference Time	0.41s
Timestamp	20260327_193434

Fault Analysis

The motorcycle overtook on the left on a single-lane road and collided with an oncoming vehicle. Both vehicles appear to share partial responsibility.

Event Timeline


Pre-Incident: Pre-incident: vehicles approaching at normal traffic speed, road clear.

Impact / Mid: Impact: sudden velocity change detected; vehicles overlap in frame.

Insurance Incident Report

On 27 March 2026, a traffic incident was recorded by the onboard dashcam unit. The footage depicts a moderate collision involving a car and a SUV at an intersection under clear conditions. The SUV failed to yield right-of-way, crossing the central divider prior to impact. Road surfaces were dry asphalt. Visibility was assessed as good. Based on the sequence of events captured, the SUV operator bears primary responsibility for the incident. Recommended follow-up: obtain police report, conduct vehicle damage assessment, and initiate third-party liability proceedings. This report is generated by an automated AI system and should be verified by a qualified claims adjuster.

Evidence Keyframes



Pre-Incident	Impact	
--------------	--------	--