

Incident Overview

Field	Value
Severity	MINOR
Vehicles	sedan, SUV
Road	wet asphalt
Weather	light rain
Visibility	moderate
VLM Model	minicpm-v
Inference Time	0.41s
Timestamp	20260327_193434

Fault Analysis

The red sedan made an abrupt lane change without signalling, directly into the path of the dashcam vehicle. The evasive braking is visible in the post-incident frame, indicating the dashcam driver attempted to avoid collision.

Event Timeline

Pre-Incident: Pre-incident: vehicles approaching at normal traffic speed, road clear.

Insurance Incident Report

On 27 March 2026, a traffic incident was recorded by the onboard dashcam unit. The footage depicts a moderate collision involving a car and a SUV at an intersection under clear conditions. The SUV failed to yield right-of-way, crossing the central divider prior to impact. Road surfaces were dry asphalt. Visibility was assessed as good. Based on the sequence of events captured, the SUV operator bears primary responsibility for the incident. Recommended follow-up: obtain police report, conduct vehicle damage assessment, and initiate third-party liability proceedings. This report is generated by an automated AI system and should be verified by a qualified claims adjuster.

Evidence Keyframes

		
Pre-Incident		