

Motor Insurance Claim Form

Policy Number: AUTO-2026-5512

Claim Number: CLM-2026-1003

Insured Name: Rohan Verma

Claimant Name: Rohan Verma

Contact Email: rohan.verma@example.com

Vehicle Registration Number: KA05MN7890

Vehicle Make: Honda

Vehicle Model: City

Date of Accident: 2026-04-21

Time of Accident: 20:45

Place of Accident: Bengaluru Outer Ring Road

Type of Loss: Third Party

Description of Accident: The insured vehicle collided with another vehicle at a traffic signal. The third-party vehicle had visible rear-side damage.

Estimated Repair Cost: INR 68000

Police Report Filed: No

Repair Estimate Attached: Yes

Damage Photo Attached: Yes

Police Report Attached: No