

Motor Insurance Claim Form

Policy Number: AUTO-2026-8841

Claim Number: CLM-2026-1001

Insured Name: Amit Sharma

Claimant Name: Amit Sharma

Contact Email: amit.sharma@example.com

Contact Phone: +91-9876543210

Vehicle Registration Number: DL01AB1234

Vehicle Make: Hyundai

Vehicle Model: i20

Vehicle Year: 2021

Date of Accident: 2026-04-18

Time of Accident: 18:30

Place of Accident: Delhi Ring Road

Type of Loss: Own Damage

Description of Accident: The vehicle hit a divider while avoiding a two-wheeler. The front bumper and left headlight were damaged.

Damaged Parts:

- Front bumper
- Left headlight

Estimated Repair Cost: INR 42000

Police Report Filed: No

Repair Estimate Attached: Yes

Damage Photo Attached: Yes

Police Report Attached: No