Lift inspection report

Lift ID: LFT-30126

Location: 83 Chapel Row, Ashdale

Inspection date: 2026-09-19

Technician: Ana Ferrer

No.	Location	Defect description	Qty
1	pit	Travelling cable, 40-core damaged	30 m
2	pit	ROPE FASTENING WEDGE SOCKET BRKN	3
3	machine room	Gearbox oil change required	1
4	car	CAR POS IND TFT COLOUR LSE	1
5	machine room	M/C ROOM LTG FITTING OUT OF ADJ	3
6	car	Car mirror loose	1