# Periodic inspection findings

**Lift no.** LFT-32808

**Address** 14 Mill Lane, Ashdale

**Date** 12/10/2026

**Inspector** Irene Navas

| Ref | Finding |
|---|---|
| F-01 | floor 7: Braille floor plate corroded (qty 4) |
| F-02 | floor 4: LDG DR CLOSER SPRING LSE (qty 3) |
| F-03 | car: CAR GUIDE SHOE INSERT FLTY (qty 2) |
| F-04 | car top: Safety gear adjustment required (qty 1) |
| F-05 | car: Car position indicator loose (qty 1) |
| F-06 | machine room: PHASE MONITORING RELAY WRN (qty 1) |
| F-07 | car: Car apron faulty (qty 1) |
| F-08 | car top: EMERG LIGHT BATT DMGD (qty 1) |
| F-09 | floor 7: LDG DR INTERLOCK ELECTRICAL CONT OUT OF ADJ (qty 3) |
| F-10 | car top: FINAL LIMIT SW UPPER LSE (qty 2) |
| F-11 | floor 3: DR GIB BRKN (qty 4) |
| F-12 | car top: PIT REFUGE SIGN NOT WKG (qty 2) |
| F-13 | floor 2: Arrival gong faulty (qty 4) |
| F-14 | car top: Emergency light battery damaged (qty 2) |
| F-15 | car: Car position indicator, dot-matrix not working (qty 1) |