Lift inspection report

Lift ID: LFT-12071

Location: 41 Orchard Way, Eastbrook

Inspection date: 2026-09-01

Technician: Diego Rubio

No.	Location	Defect description	Qty
1	machine room	CONTROL CAB FAN FLTY	1
2	floor 8	Door operator belt worn	1
3	car	Car position indicator, TFT colour not working	1
4	car	Car guide shoe insert, roller damaged	4
5	floor 8	ARRIVAL GONG NOT WKG	1
6	machine room	LOAD WEIGHING SENS LSE	1
7	car top	Alarm push button broken	2
8	building	Graffiti on the car walls	1
9	building	Stairwell lighting out next to the landing door	1
10	machine room	Hydraulic hose, 1 m worn	2
11	floor 6	Landing door closer, spring faulty	1
12	car	CAR MIRROR LSE	1