Branch maintenance form

Unit no.	LFT-46000	**Date of visit**	22 Sep 2026
Site address	62 Larch Street, Northgate	**Engineer**	Jorge Campos

Pos.	Component	Observation	Units
1	Car top inspection box	corroded, car	1
2	Car top inspection box	out of adjustment, car	1
3	LOAD WEIGHING SENS	FLTY, machine room	1
4	Unintended car movement detector	worn, car top	1
5	Control cabinet fan	out of adjustment, machine room	1
6	Traction sheave, regrooving	required, machine room	1
7	Machine room window glass cracked	building	1