Lift inspection report

Lift ID: LFT-25523

Location: 18 Quarry Road, Ashdale

Inspection date: 2026-09-01

Technician: Marta Campos

No.	Location	Defect description	Qty
1	floor 9	Landing door closer, weight and cable loose	4
2	machine room	Earthing conductor repair required	2
3	pit	GOV ROPE 8 MM FLTY	90 m
4	car top	Emergency telephone, GSM module damaged	1
5	car	Car top inspection box not working	1
6	car	Car handrail, stainless steel faulty	3
7	building	Graffiti on the car walls	1
8	car top	Slack rope switch not working	1
9	floor 8	HALL POS IND DOT-MATRIX LSE	3
10	car	CAR APRON DMGD	1
11	car	Car floor covering not working	3 m2
12	car	Car LED ceiling panel, 300 x 300 mm worn	4
13	pit	Pit ladder not working	1