Branch maintenance form

Unit no.	LFT-37678	**Date of visit**	04 Sep 2026
Site address	78 Harbour Avenue, Westmere	**Engineer**	Clara Molina

Pos.	Component	Observation	Units
1	Car floor covering, vinyl	broken, car	4 m2
2	Pigeons nesting on the machine room roof	building	1
3	Shaft lighting fitting	out of adjustment, pit	2
4	PIT LADDER	OUT OF ADJ, pit	1
5	Brake coil	corroded, machine room	2
6	CONTROL BOARD RELAY	DMGD, machine room	3
7	CAR TOP INSPECTION BOX	CORR, car	1