Lift inspection report

Lift ID: LFT-11280

Location: 52 Quarry Road, Ashdale

Inspection date: 2026-10-04

Technician:

No.	Location	Defect description	Qty
1	car	CAR EMERG LIGHT FLTY	2
2	car top	OVERSPEED GOV FLTY	1
3	machine room	Brake coil loose	1
4	car	Car apron corroded	1
5	machine room	Control cabinet fan out of adjustment	2
6	car top	Alarm push button worn	1
7	car	CAR POS IND BRKN	1
8	pit	CWT GUIDE SHOE INSERT SLIDING BRKN	3
9	building	Graffiti on the car walls	1
10	machine room	Hydraulic hose, 1 m not working	2
11	floor 7	Hall lantern broken	4