Lift inspection report

Lift ID: LFT-19316

Location: 41 Orchard Way, Northgate

Inspection date: 2026-10-16

Technician: Pablo Rubio

No.	Location	Defect description	Qty
1	car	CAR GUIDE SHOE INSERT LSE	3
2	floor 1	Landing door hanger out of adjustment	4
3	car	Car top inspection box loose	1
4	pit	Rail lubricator, counterweight out of adjustment	4
5	floor 1	Door operator motor, AC damaged	1
6	machine room	Hydraulic oil corroded	80 l
7	pit	TRAV CBL WRN	10 m
8	floor 7	HALL LANTERN CORR	2
9	machine room	Brake coil out of adjustment	2
10	machine room	Motor encoder, incremental loose	1
11	machine room	HYD HOSE CORR	2
12	floor 6	Car door roller, 60 mm corroded	3
13	pit	GOV ROPE 8 MM WRN	40 m
14	floor 5	Hall lantern out of adjustment	4

No.	Location	Defect description	Qty
15	floor 9	Hall position indicator, dot-matrix out of adjustment	4
16	car	Car guide shoe insert, roller damaged	4
17	machine room	Traction sheave, regrooving required	1
18	pit	Rail lubricator, car loose	3
19	machine room	Earthing conductor repair required	3
20	building	Water ingress in the pit from the building drainage	1