Lift inspection report

Lift ID: LFT-80554

Location: 118 Quarry Road, Fairholm

Inspection date: 2026-10-23

Technician: Irene Ferrer

No.	Location	Defect description	Qty
1	car top	CAR ROOF BALUSTRADE WRN	1
2	car top	Emergency telephone, landline unit broken	1
3	machine room	Hydraulic oil loose	110 l
4	building	Pigeons nesting on the machine room roof	1
5	floor 8	HALL LANTERN NOT WKG	2
6	machine room	Brake lining, drum brake broken	1
7	floor 5	Door operator motor, AC broken	1
8	machine room	LOAD WEIGHING SENS OUT OF ADJ	1