Branch maintenance form

Unit no.	LFT-46302	**Date of visit**	13 Sep 2026
Site address	11 Chapel Row, Westmere	**Engineer**	Ana Vidal

Pos.	Component	Observation	Units
1	Owner asks for an extra stop at the basement	building	1
2	CAR OP PANEL PUSH BTN	FLTY, car	2
3	Car mirror	worn, car	1
4	HYD VALVE SEAL KIT	DMGD, machine room	1
5	CONTROL CAB FAN	CORR, machine room	2
6	BUFFER CAR SPRING	FLTY, pit	1
7	LIGHT CURTAIN SINGLE-SIDE	FLTY, floor 9	1
8	Water ingress in the pit from the building drainage	building	1