# Branch maintenance form

| | | | |
|---|---|---|---|
| **Unit no.** | LFT-45774 | **Date of visit** | 15 Oct 2026 |
| **Site address** | 71 Harbour Avenue, Northgate | **Engineer** | Jorge Ortega |

| Pos. | Component | Observation | Units |
|---|---|---|---|
| 1 | Rail lubricator | broken, pit | 4 |
| 2 | Machine room lighting fitting | damaged, machine room | 4 |
| 3 | LIFT MAIN SW | FLTY, machine room | 1 |
| 4 | Unintended car movement detector | out of adjustment, car top | 1 |
| 5 | Door zone switch | faulty, machine room | 1 |
| 6 | Floor levelling sensor | not working, machine room | 1 |
| 7 | Buffer | damaged, pit | 2 |
| 8 | Door operator motor | broken, floor 3 | 1 |

| Pos. | Component | Observation | Units |
|---|---|---|---|
| 9 | Car ventilation fan | not working, car | 1 |
| 10 | Car roof balustrade | loose, car top | 1 |
| 11 | Car door contact | not working, floor 1 | 2 |
| 12 | Main contactor | corroded, machine room | 3 |
| 13 | FLOOR LEVELLING SENS OPTICAL | DMGD, machine room | 2 |
| 14 | Deflector pulley bearing | broken, machine room | 2 |
| 15 | Owner asks for an extra stop at the basement | building | 1 |
| 16 | Pit refuge sign | worn, car top | 1 |
| 17 | Hydraulic cylinder packing | out of adjustment, machine room | 1 |
| 18 | M/C ROOM LTG FITTING | NOT WKG, machine room | 1 |