

SolarSight AI

Official Maintenance & Inspection Report

Inspection ID: 573dab34...af01

Date: May 09, 2026 - 06:09:24

Status: Completed

Analyzed Solar Panel Image:



■ ■ Detected Anomalies:

- Hotspot (96% confidence) at Unknown Panel Location
- Micro-crack (44% confidence) at Unknown Panel Location
- Micro-crack (68% confidence) at Unknown Panel Location