

SolarSight AI

Official Maintenance & Inspection Report

Inspection ID: db950881...5e29

Date: May 09, 2026 - 06:25:02

Status: Completed

Analyzed Solar Panel Image:



■ ■ Detected Anomalies:

- Micro-crack (85% confidence) at Unknown Panel Location
- Soiling (30% confidence) at Unknown Panel Location
- Micro-crack (96% confidence) at Unknown Panel Location