

SolarSight AI

Official Maintenance & Inspection Report

Inspection ID: de060b49...0c32

Date: May 09, 2026 - 06:32:17

Status: Completed

Analyzed Solar Panel Image:



■ Detected Anomalies:

- Micro-crack (50% confidence) at Unknown Panel Location

Analyzed Solar Panel Image:



Analyzed Solar Panel Image:



✓ No critical faults detected on this image.