ISSUE REGISTER

Project Name: Project Manager:

Raise Raised				Issue Description			Issue Resolution				
ID	Date Raised	Raised By	Receive d By	Description of Issue			Action	Owner	Outcome	Date for Resolution	Date Resolved
3955970	2010/10/22	Nico		Remove Sub assembly S32 & re-install on correct pos	sition		Remove Sub assembly S32 Grind all excess metal work Repaint all metal parts				