

Fire Risk Assessment

[Click Here to Reset Form](#)

Property Details



Address:	Mulberry Housem 21 High Park Road, Broadstone, Dorset. BH18 9DE		
Name of Owner:	Tina & Jonathan Brown	Property ID:	1082567
Assessor / Owner Signature: Please Print Name	Tina Brown	Date:	16 / 06 / 2024

Description of Property



Type of Property: (e.g. 2 storey house/flat/bungalow)	2 storey house		
Number of exits from the property & location:	3 exits - Front, Back and side Kitchen doors		
Does the exit involve the use of a shared area? (e.g. stairs)	YES ☐	NO ☒	
Have there been any fires in the property in the last 3 years?	YES ☐	NO ☒	

Hazards



Identify hazards and steps taken to reduce the risk. Complete any actions on the last page.

What is the primary method of heating?	When was the last service undertaken?
Gas Central Heating	03 / 10 / 2023
What other sources of heating are present?	When was the last service undertaken?
Log Burner	12 / 08 / 2023
Where gas / coal / wood / oil are present in the property, is a carbon monoxide detector present on each floor?	YES ☒ NO ☐
State location of the detectors:	
Lounge/Diner (next to log burner) & Garage (next to Boiler)	
Has the electrical wiring been checked by a qualified electrician every 5 years?	YES ☒ NO ☐
What was the date of the last electrical check?	02 / 03 / 2023

Fire Risk Assessment

What electrical appliances are present and have these been PAT tested annually?

Appliance	Present?		Date of last PAT test
Lamps throughout property	YES ☒	NO ☐	06 / 10 / 2022
Washing Machine / Dryer / Fridge / Freezer	YES ☒	NO ☐	06 / 10 / 2022
Dishwasher / Oven	YES ☒	NO ☐	06 / 10 / 2022
Kettle / Toaster / Microwave	YES ☒	NO ☐	06 / 10 / 2022
Juicer / Food Mixer	YES ☐	NO ☒	06 / 10 / 2022
Extension Leads	YES ☒	NO ☐	06 / 10 / 2022
TV's / Radio	YES ☒	NO ☐	06 / 10 / 2022
Hairdryer / Clock-Radio / Iron	YES ☒	NO ☐	06 / 10 / 2022

Other: (list)	Date of last PAT test

Deep fat fryers are not permitted.

What is the main fuel fired cooking equipment that has been provided? **Gas Hob & Electric Oven**

What is the date of the service? **03 / 10 / 2023**

Is there a BBQ provided for guest use? YES ☒ NO ☐

What safety measures are available?

Water tap next to BBQ. 1 x Fire extinguisher in the lounge near woodburner and 1 x fire extinguisher in the kitchen with 1 x Fire blanket.

Smoking is not permitted in the property. What facilities are available if smoking is permitted outside? (e.g. Garden / Patio)

No smoking allowed on property

List the location of any candles

None

Candles should be placed in receptacles higher than the flame, otherwise are not allowed. Consider the use of battery operated candles. Fireworks are not permitted on the property.

Fire Risk Assessment

Fire Systems & Procedures



Fire Detection

Describe the type and level of fire detection (e.g. smoke detectors/heat detectors), the location, the method of checking they are still operational and any formal checks undertaken by contractors

#	Smoke or Heat Detector	Type (tick one)			Location
		Battery Operated	Radio Interlinked	Hard Wired	
1	Smoke ☒	☐	☐	☒	Hall
2	Smoke ☒	☐	☐	☒	Kitchen
3	Smoke ☒	☐	☐	☒	Upstairs Landing
4	Choose... ☐	☐	☐	☐	
5	Choose... ☐	☐	☐	☐	
6	Choose... ☐	☐	☐	☐	

#	Operation Check	Formal Checks
1	Tested by owners on 16th June 2024	
2	Tested by owners on 16th June 2024	
3	Tested by owners on 16th June 2024	
4		
5		
6		

Where are the fire extinguishers located and when were they last serviced?

Location	Last Service Date
Kitchen (never been used)	09 / 01 / 2021
In open cupboard under log burner (never been used)	09 / 01 / 2021

There should be at least one CO2 extinguisher on each floor and at least one fire blanket in the kitchen.

Suppression Systems

Has a fire suppression system been installed? YES ☐ NO ☒

Describe the method of checking the system is working and any formal checks by contractors

Fire Exits

Can the main door be opened from the inside without a key? YES ☒ NO ☐

Is a fire action plan available for guests? YES ☒ NO ☐

FOR WALES ONLY - It is the owner's responsibility to contact their local planning/building control department to check the requirements for installation of a fire suppression system

Fire Risk Assessment

Housekeeping and Furniture

 Are the bins emptied on a regular basis?	YES ☒	NO ☐
 Is the level of housekeeping in the property satisfactory?	YES ☒	NO ☐
 Does all of the furniture comply with the furniture regulations?	YES ☒	NO ☐
 Is the garage locked, preventing guest access? (if applicable)	N/A ☐	YES ☒ NO ☐

Emergency Lighting

 Is emergency lighting fitted?	YES ☐	NO ☒	 If so, how?	Choose... ☐
 Is there adequate lighting on fire exit routes? (e.g. stairs & adequate handrails)	YES ☒	NO ☐		
 Describe the method of checking it is working and any formal checks undertaken by contractors				
 Are there torches available for use?	YES ☒	NO ☐		

Miscellaneous

 List any other comments relating to fire safety for the property	
 List persons who could be at risk using the property	Disabled or elderly persons if sleeping upstairs. We have 1 bedroom downstairs for this use. Unaccompanied children.
 What is the maximum number of guests and visitors permitted at the property?	Guests: 10 Visitors:

Actions



Action	To be completed by	Completion Date
Gas Safety check due OCT 24 (contacted Plumber/Gas Engineer)	03/10/2024	
Log Burner clean and safety check - booked for 15/10/24	15/10/24	