

Property & Regulation: Housing Property & Assets

HSN 03: % of Dwellings Meeting SHQS

84.3%
2023-24

 Deteriorating & Decreasing



HSN 04b: Average Time Taken to Complete Non-Emergency Repairs

6.85 Days
2023-24

 Deteriorating & Increasing




HSN 05a: % of Council Dwellings that are Energy Efficient

94.1%
2021-22

 Improving & Increasing




HSN 03 % of Dwellings Meeting SHQS




Period	Value	Rank
2013-14	79.4%	#3
2014-15	95.5%	#1
2015-16	97.2%	#1
2016-17	98.1%	#1
2017-18	99.2%	#1
2018-19	99.6%	#1
2019-20	96.5%	#2
2020-21	90.8%	#4
2021-22	80.9%	#2
2022-23	87.0%	#1
2023-24	84.3%	#2

HSN 04b Average Time Taken to Complete Non-Emergency Repairs



Period	Value	Rank
2013-14	7.60 Days	#4
2014-15	5.40 Days	#2
2015-16	4.86 Days	#1
2016-17	6.81 Days	#3
2017-18	4.62 Days	#1
2018-19	4.59 Days	#1
2019-20	3.67 Days	#1
2020-21	3.16 Days	#1
2021-22	6.38 Days	#1
2022-23	6.55 Days	#2
2023-24	6.85 Days	#2

HSN 05a % of Council Dwellings that are Energy Efficient



Period	Value	Rank
2015-16	82.9%	#2
2016-17	81.9%	#2
2017-18	85.2%	#1
2018-19	90.4%	#1
2019-20	92.2%	#1
2020-21	93.1%	#1
2021-22	94.1%	#1