

In-Out Inspection Date: 2016-09-24



Inspection Details

Address: 163 Koedoe Street Wierda Park

Tenant: Eckardt Briedenhann

Agent: Stefan Delport

Date of inspection: 2016-09-24
Type of inspection: In-Out Inspection

Inspection Results

Front Door

Area Item	Condition	Repair Needed
Door		
Door Key Code	Excellent	У
Door Stopper	Excellent	у
Outside Light	Excellent	у
Door Frame	Excellent	У
Door Lock	Excellent	У

Bedroom 2

Area Item	Condition	Repair Needed
Door	Excellent	У
Door Lock	Excellent	У

Bedroom

Area Item	Condition	Repair Needed
Door		

Hallway

Area Item	Condition	Repair Needed	
Carpet/Tiles		·	
Ceiling			
Skirting			
Light Bulp			
Light Fitting			
Light Fixture			
Light Switch			
Electrical Plugs			
Window			
Walls			
Nails, Screws & Hooks			
Cupboard			

Copyright: Paideia Solutions 2016





Area Item	Condition	Repair Needed	
Cupboard Handles			
Cupboard Hinges			
Shelves of Cupboard			
Window Rail			
Window Handles & Sliders			

Bedroom 1

Area Item	Condition	Repair Needed	
Door Key Codes			
Door Stopper			
Carpet / Tiles			
Ceiling			
Skirting			
Light Bulps			
Light Fitting & Cover			
Light Switch			
Electrical Plugs			
Window			
Window Handles & Slider			
Window Rail			
Walls			
Door			
Door Lock			
Door Frame			
Nails, Screws & Hooks			
Air Conditioner			
Cupboard			
Cupboard Hinges			
Cupboard Handles			
Shelves of Cupboard			

Copyright: Paideia Solutions 2016