8D report

Customer plant:	TNS Servis	**Supplier:**	AVO Carbon Germany	**Date of claim:**	29.08.2025
Customer contact:	Veronika PAVELKOVA	**AVO contact:**	Gunther Luschtinetz		
Customer reference:	RMA-2025-033	**AVO reference:**	250809		

QUICK RESPONSE (D1-D3)

This document must be issued within 24 hours after claim notification

D 1. Description of the problem

1.a What is the problem? Use 5W+2H to describe what is the current situation.

Problem description	Wires of carbon are deformed and not suitable for automatic line assembly.	What happened	Wires of carbon are deformed and not suitable for automatic line assembly.
		Why is it a problem	Causes downtime because material gets stucked in linear feeder?
Incident type	Customer claim		
Part number AVO	1026151	When did it happen	29.08.2025
Part number Customer	3134320622	Who detected it	?
Batch number	286882	Where was it detected	?
Recurrence	Non-recurrent	How was it detected	Visually
Defect S/R	No	How many bad parts	min. 6
Standard process used	Yes		
When was the part produced?	Pressing machine => 14662: 15.07.2025-18.07.2025 Grinding machine => SSS 3255: 23.07.2025-28.07.2025		

nOK part picture/ sketch

OK part picture/ sketch

1.b Problem solving team

Name	Position	Location	E-mail
Gunther Luschtinetz	Quality Management	AVO Germany	gunther.luschtinetz@avocarbon.com
Joachim Gehl	Quality Management	AVO Germany	joachim.gehl@avocarbon.com
Martin Röhr	Production	AVO Germany	
Mustafa Yorulmaz	Production	AVO Germany	
Khaled amri	Logistic	AVO Germany	

1.c Tools to use

☐ **Ishikawa** ☐ **5why's** ☐ **LLC** ☐ **Audit** ☐ **Other**

1.d First analyse of problem / potential root causes

Potential root cause(s): In analysis

If you use our expressnumber, please use only economic express.

Samples of nok parts required in plant for analyse: Yes

Express shipping number account: FedEx 186141300

D 2. Risk on similar products and processes

Can this defect happen on similar parts?

Other family product	---
Other line	---
Other tools/work station	---
Other	---

Comments (compulsory, if yes)

D 3. Containment

Sorting criterias (add additional sheets if needed)

Location in the supply chain	N° of involved parts	N° parts sorted	N° nok parts	Ppm	Date	Responsible
Parts at customer	5.000	---	---	---	---	eronika PAVELKOV
Parts in transport	---	---	---	---	---	---
Parts at AVO Germany stock	---	---	---	---	---	Gunther Luschtinetz
Parts at AVO production	---	---	---	---	---	---

First contained shipment information

Immediate actions to prevent production and delivery of nok parts ?

Containment actions	Responsible	Date planned	Date closed
Register the complaint + Quality alert	Gunther Luschtinetz	08.09.2025	08.09.2025
Check the production-, quality- and maintenance data	Gunther Luschtinetz	08.09.2025	08.09.2025
Information of all department leader during shop floor meeting QRQC	Joachim Gehl	08.09.2025	08.09.2025