

SWIN Analysis
Complete

Deviation vs Standard

IS / IS NOT Analysis
Complete

💡 Identify what IS affected vs what IS NOT to isolate critical factors.

- Identify what IS affected vs what IS NOT to isolate critical factors

Product

✓ IS A PROBLEM

CEM Carbon brush PN 3134 S20725

CEM Carbon brush PN 3134 320721

X IS NOT A PROBLEM

Other part numbers / other products (PN = 3134320725)

 Time

Detected on 2020-04-01 at BOSCH plant (OEM Line) during customer assembly process

X IS NOT A PROBLEM

No occurrence before 2026-02-23

 Lact

7/12 & PROBLEM

Packaging LOT K26824

X IS NOT A PROBLEM

Other packaging L0Ts (+ K26824)

 Pattern

IT'S A PROBLEM

26 mixed/unknown carbon brushes found out of 10,000 pcs inspected (100% inspection) in LOT K26B24

IT IS NOT A PROBLEM

9,974 pcs in the same inspection were OK (no mix.

👉 **start cost** **no cost**