8D report

Customer plant:	Dunkermotoren	**Supplier:**	AVO Carbon Germany	**Date of claim:**	14.05.2025
Customer contact:	Hardy Huber	**AVO contact:**	Joachim Gehl		
Customer reference:	Q2-200232757	**AVO reference:**	250502		

QUICK RESPONSE (D1-D3)
This document must be issued within 24 hours after claim notification

D 1. Description of the problem

1.a What is the problem? Use 5W+2H to describe what is the current situation.

Problem description	1 Karton mit Fremdkohlebürste geliefert	What happened	1 Karton mit Fremdkohlebürste geliefert
		Why is it a problem	KB passt nicht in den Bürstenträger
Incident type	Customer claim		
Part number AVO	1020511	When did it happen	?
Part number Customer	27579.52268 / 1020511	Who detected it	?
Batch number	? Nicht mitgeteilt	Where was it detected	?
Recurrence	Non-recurrent	How was it detected	Sichtprüfung
Defect S/R	No	How many bad parts	4000 (=1 Card box)
Standard process used	Yes		
When was the part produced?	Pressing machine => nicht relevant Grinding machine => nicht relevant		

nOK part picture/ sketch



OK part picture/ sketch

1.b Problem solving team

Name	Position	Location	E-mail
Joachim Gehl	Quality Management	AVO Germany	joachim.gehl@avocarbon.com
Gunther Luschtinetz	Quality Management	AVO Germany	gunther.luschtinetz@avocarbon.com
Martin Röhr	Production	AVO Germany	
Mustafa Yorulmaz	Production	AVO Germany	
Khaled amri	Logistic	AVO Germany	

1.c Tools to use

☐ **Ishikawa** ☐ **5why's** ☐ **LLC** ☐ **Audit** ☐ **Other**

1.d First analyse of problem / potential root causes

Potential root cause(s): Vermischung im Versandbereich beim Kommissionieren

If you use our expressnumber, please use only economic express.

Samples of nok parts required in plant for analyse: Yes

Express shipping number account: FedEx 186141300

D 2. Risk on similar products and processes

Can this defect happen on similar parts?

		Comments (compulsory, if yes)
Other family product	Yes	Komplette Kartons können nur beim Kommissionieren bzw. wo durchzuführen, beim Tarieren.
Other line	Yes	
Other tools/work station	---	
Other	---	

D 3. Containment

Sorting criterias (add additional sheets if needed)

Location in the supply chain	N° of involved parts	N° parts sorted	N° nok parts	Ppm	Date	Responsible
Parts at customer	0	---	---	---	---	---
Parts in transport	0	---	---	---	---	---
Parts at AVO Germany stock	73.000	73000	0	0	16.05.2025	Khaled Amri
Parts at AVO production	---	---	---	---	---	---

First contained shipment information

Immediate actions to prevent production and delivery of nok parts ?

Containment actions	Responsible	Date planned	Date closed
Register the complaint + Quality alert	Joachim Gehl	20.05.2025	20.05.2025
Check the production-, quality- and maintenance data	Joachim Gehl	20.05.2025	20.05.2025
Information of all department leader during shop floor meeting QRQC	Joachim Gehl	21.05.2025	21.05.2025