Claim Management Panel

Supplier: **AVO Carbon France (NMAP551841)**

Type: **I - Information**

Problem description: **pin of tin on the soldering pad, risk of contamination**

Claim reference: **NMAP/551841/2/2024/1662**

Settings

C2/C3 REMINDER PANEL

(QR) D2-D3 Defualt Due Date :	**2/5/2024**	1:26:04 PM (your local time)	D2-D3 Revised Due Date:	(QR) D2-D3 Actual Date:	**2/5/2024**	4:27:18 PM (your local time)	(QR) D2-D
D4 Default Due Date :	**2/7/2024**	1:26:04 PM (your local time)	D4 Revised Due Date :	D4 Actual Date :	**6/27/2024**	4:26:18 PM (your local time)	D
D5-D6 Default Due Date:	**2/16/2024**	1:26:04 PM (your local time)	D5-D6 Revised Due Date:	D5-D6 Actual Date:	**6/28/2024**	10:59:32 AM (your local time)	D5-D
D7-D8 Default Due Date:	**2/16/2024**	1:26:04 PM (your local time)	D7-D8 Revised Due Date C2/C3:	D7-D8 Actual Date:	**6/30/2024**	8:56:12 AM (your local time)	D7-D



NOTIFICATIONS SENT

0 Result(s)

NIDEC APPROVALS & REFUSALS HISTORY

Steps approved

Step	Date of validation	User name
D8	6/30/2024	Marwen Haggui
D1	2/2/2024	Dominik Dudek
D4 Validation	6/28/2024	Dominik Dudek
D2	6/27/2024	Marwen Haggui
D2-D3 Validation	2/6/2024	Dominik Dudek
D3	6/27/2024	Marwen Haggui
D4	6/27/2024	Marwen Haggui
D5	6/28/2024	Marwen Haggui
D5-D6 Validation	6/28/2024	Dominik Dudek
D6	6/28/2024	Marwen Haggui
D7	6/30/2024	Marwen Haggui
D7-D8 Validation	7/1/2024	Dominik Dudek
8D closed	7/11/2024	Dorota Siekaniec
8D Closing	7/11/2024	Dorota Siekaniec
Creation	2/2/2024	Dominik Dudek

15 Result(s)

Steps rejected

0 Result(s)

Forum

Filter

Keywords:

0 Result(s)

Quick Response (D1-D3)

ALERTS

-Component without PPAP

Plant issued a claim:	NIDEC MOTORS & ACTUATORS (POLAND) Sp z o.o.	Supplier:	**AVO Carbon France (NMAP551841)**	Date of Claim:	**2/2/2024**
Customer Contact:	**Dudek Dominik**	SAP Vendor Code:	**551841**	Date of QR:	**2/5/2024**
Claim reference:	**NMAP/551841/2/2024/1662**	Author:	**DUDEK Dominik**	Update of QR:	**2/5/2024**
Status:	**Closed**	Type:	**I - Information**		
		CLAIM PPM:	0.00		

D1-D3 evaluation score: 22

D1. Description of the problem

1.A WHAT IS THE PROBLEM ? USE 5W+2H TO DESCRIBE WHAT IS THE CURRENT SITUATION.

Problem description:	**pin of tin on the soldering pad, risk of contamination**	What happened?:	**pin of tin on the soldering pad, risk of contamination**
Part Number & Description:	Brush mounting plate assy (503-772-99-99)	Why is it a problem?:	**pin of tin on the soldering pad, risk of contamination**
Traceability of nok parts:	**Batch 2401151, ASN 180382383**	When did it happen? :	**1/30/2024** 12:00:00 AM (your local time)
Recurrence:	**Recurrent defect**	Who detected it?:	**operator**
Defect S/R:	**No**	Where was it detected? :	**CM4 line**
		How was it detected?:	**visually**
		How many parts ?:	**1.00**

nok part picture / sketch:

ok part picture / sketch:

Other files::

1.B SUPPLIER PROBLEM SOLVING TEAM

Supplier Team

Add an existing contact:

Name		Contact	Email	Phone	Cell Phone	Fax	Position	Profile	Status
Haggui Marwen		• marwen.haggui@avocarbon.com	marwen.haggui@avocarbon.com	+21656057189	+21656057189		Customer Quality	Supplier	Active

NidecTeam

Contact	Email	Profile
DUDEK Dominik	dominik.dudek@nidec-ma.com	{profile} Local Quality (Local SQE) (Full) (Claim)

1.C TOOL TO USE (DEFINED BY NIDEC)

Ishikawa: ☑ FTA: ☑ 5 Whys : ☑ LLC: ☑ Audit: ☐ Other: ☐

1.D PROBLEM DESCRIPTION FROM SUPPLIER / FIRST ANALYSE OF PROBLEM / POTENTIAL ROOT CAUSES

Problem description from Supplier: **pin of tin on the soldering pad, risk of contamination**

Samples of nok parts required at supplier location: ☑ Express shipping supplier account: **regular truck**

D2. Risk on similar products and processes

Can this defect happen on similar parts?: Comments (compulsory if yes): **all reference CM4**

Other family product: ☐

Other machine: ☐

Other tooling: ☐

Other Nidec plants: ☐

Other: ☐

D3. Containment

WHAT ARE THE ACTIONS TO DETECT ALL NON-CONFORMING PARTS IN THE PROCESS FLOW?

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Delivery note and batch #	Responsible
Parts at Nidec plant	2,663.00	0.00	1.00			Nidec
Parts at Nidec logistics platform	0.00	0.00	0.00			
Parts at Nidecs customer (C1 claim)	0.00	0.00	0.00			

Location in the process flow	Nb to be sorted	Nb parts sorted	Nb nok parts	Date	Responsible	Delivery note and batch #
Parts in transport	0.00	0.00	0.00			
Parts at supplier / supplier platform	7,000.00	0.00	0.00	2/5/2024	Supplier	
Parts at sub-supplier	0.00	0.00	0.00			
Other Nidec plant/s	0.00	0.00	0.00			

4 Result(s)

How are the ok parts identified?: **'100 Sorted regarding pin of tin on the soldering pad, risk of contamination**

First contained shipment information: **delevery for week 06**

How are the ok paletts identified?: **With orange identification (standard NIDEC)**

How are the ok parts identified? :: Securing identification.pdf

WHAT ARE THE IMMEDIATE ACTIONS TO PREVENT PRODUCTION/DELIVERY OF NOK PARTS?

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
Express delivery to Nidec to avoid production stop				
Nidec suspect stocks to be sent to supplier				

Actions	Nidec decision	Responsible	Date Plan.	Date Clos.
display quality alert	Not required	Supplier	2/2/2024	2/2/2024
QRQC meeting with all the team	Not required	Supplier	2/2/2024	2/2/2024

2 Result(s)