

CR-7BC12A TC155

Compliance Report



| Map Height & Width: | 11.00 X 8.50 in | | |
|---------------------|------------------------------|--|--|
| Time Zone: | Pacific Time (US and Canada) | | |
| Exclusion Radius: | 0 m | | |
| Report Mode: | Standard | | |
| NE Lat & NE Long | 37.44794 X -122.18017 | | |
| SW Lat & SW Long | 37.43945 X -122.19004 | | |

| | GAP Investigation Complete | | | | | |
|---|----------------------------|--|--|--|--|--|
| CGI Investigation Complete | | | | | | |
| Report Creation Date 11/11/2015 09:16:48 PM PST | | | | | | |
| Approver Name | | | | | | |

LISA Investigation Complete

Approver Signature Date


Date Printed: 11/11/2015 09:16:48 PM PST Report Author: Administrator Software Version: 2.2.7f4dad4 1 of 3



3

Beta7 - Chevy

CR-7BC12A TC155



Date Printed: 11/11/2015 09:16:48 PM PST Report Author: Administrator Software Version: 2.2.7f4dad4 2 of 3

0.56

2.47

02/17/2015 08:26:17 PM PST

PICARRO Surveyor™ Surveys Mains and Services at Driving Speeds

| CR-7BC12A | |
|-----------|--|
| TC155 | |

| LISA# | Surveyor | Date/Time | Amplitude (ppm) | Concentration (ppm) | Field Notes |
|-------|---------------|----------------------------|--------------------|------------------------|-------------|
| 4 | Beta7 - Chevy | 02/17/2015 08:24:11 PM PST | 0.46 | 2.37 | |
| 5 | Beta7 - Chevy | 02/17/2015 07:27:03 PM PST | 0.43 | 2.37 | |
| 6 | Beta7 - Chevy | 02/17/2015 08:08:51 PM PST | 0.31 | 2.27 | |
| 7 | Beta7 - Chevy | 02/17/2015 08:24:41 PM PST | 0.28 | 2.21 | |
| 8 | Beta7 - Chevy | 02/17/2015 08:10:15 PM PST | 0.25 | 2.24 | |
| 9 | Beta7 - Chevy | 02/17/2015 08:03:15 PM PST | 0.17 | 2.11 | |
| 10 | Beta7 - Chevy | 02/17/2015 08:20:41 PM PST | 0.16 | 2.09 | |
| 11 | Beta7 - Chevy | 02/17/2015 08:20:58 PM PST | 0.1 | 2.02 | |

Date Printed: 11/11/2015 09:16:48 PM PST Software Version: 2.2.7f4dad4 3 of 3 Report Author: Administrator