PICARRO Surveyor™

Surveys Mains and Services at Driving Speeds

Compliance Report

Map Height & Width:	11.00 X 8.50 in
Time Zone:	Pacific Time (US and Canada)
Exclusion Radius:	0 m
Report Mode:	Standard
Boundary	IF00000000000000037623 DistrictPlat-3347-A7

◯ LISA Investigation Complete

◯ GAP Investigation Complete

◯ CGI Investigation Complete

Report Creation Date   11/11/2015 06:07:18 PM PST

_____

Approver Name

_____   _/_ _/_

Approver Signature   Date

PICARRO
Surveyor™
Surveys Mains and Services at Driving Speeds

Layers

Asset				Boundary	
Copper	◯	PE Plastic	◯	District Plat	◯
Protected Steel	◯	Cast Iron	◯	District	◯
Un-protected Steel	◯	Other Plastic	◯		

View Table

Selected Views

View Name	Show LISAs	Show FOV	Show Breadcrumb	Show Indications	Show Isotopic Analyses	Show Field Notes	Show Gaps	Show Assets	Show Boundaries	Base Map
View 1	✓	✗	✗	✗	✗	✗	✓	✗	✗	Map

Selected Driving Surveys

Start Date/Time	End Date/Time	Duration (min)	User Name	Surveyor	Analyzer	Tag	FOV	Indication	LISA	Analysis	Stability Class
02/17/2015 06:41:22 PM PST	02/17/2015 11:08:16 PM PST	267	kdu@pge.com	Beta7 - Chevy	FEDS2043	menlo ory	🔵	⚪	🟡	🔴	E

Gap Table

☐ A1	☐ B1	☐ C1	☐ D1	☐ E1	☐ F1	☐ G1	☐ H1	☐ I1	☐ J1	☐ K1	☐ L1
☐ A2	☐ B2	☐ C2	☐ D2	☐ E2	☐ F2	☐ G2	☐ J2	☐ K2	☐ L2	☐ A3	☐ B3
☐ D3	☐ E3	☐ F3	☐ G3	☐ L3	☐ A4	☐ D4	☐ E4	☐ F4	☐ H4	☐ I4	☐ J4
☐ L4	☐ A5	☐ D5	☐ E5	☐ F5	☐ G5	☐ H5	☐ I5	☐ J5	☐ L5	☐ D6	☐ E6
☐ F6	☐ G6	☐ H6	☐ I6	☐ J6	☐ K6	☐ L6	☐ A7	☐ D7	☐ E7	☐ G7	☐ L7
☐ A8	☐ D8	☐ E8	☐ F8	☐ L8	☐ A9	☐ B9	☐ C9	☐ D9	☐ E9	☐ F9	☐ K9
☐ L9	☐ B10	☐ C10	☐ D10	☐ E10	☐ G10	☐ H10	☐ I10	☐ J10	☐ K10	☐ L10	☐ A11
☐ C11	☐ D11	☐ H11	☐ I11	☐ J11	☐ K11	☐ L11	☐ A12	☐ C12	☐ D12	☐ H12	☐ I12
☐ J12	☐ K12	☐ L12	☐ A13	☐ B13	☐ C13	☐ D13	☐ E13	☐ F13	☐ G13	☐ I13	☐ J13
☐ K13	☐ L13	☐ A14	☐ B14	☐ C14	☐ D14	☐ F14	☐ G14	☐ H14	☐ K14	☐ A15	☐ B15

PICARRO
Surveyor™

Surveys Mains and Services at Driving Speeds

☐ C15　☐ G15　☐ H15　☐ I15　☐ K15　☐ L15　☐ A16　☐ B16　☐ D16　☐ F16　☐ G16　☐ H16

☐ I16　☐ J16　☐ K16　☐ L16　☐ A17　☐ B17　☐ C17　☐ D17　☐ E17　☐ F17　☐ G17　☐ H17

☐ I17　☐ J17　☐ K17　☐ L17