

IV-6AD1AB TC169

Investigation Report

Lisa Investigation Table

Lisa#	Amplitude	Investigated	Leak Found	Investigation Date/Time	Investigator
1	3.42	×	×		
2	0.74	×	×		
3	0.56	×	X		
4	0.46	×	X		
5	0.43	X	X		
6	0.31	×	X		
7	0.28	×	X		
8	0.25	S	X		
9	0.17	X	X		
10	0.16	×	X		
11	0.10	×	×		

Software Version: 2.2.7f4dad4