

Pos	Item name	Item number	Service manual	Service to be done by
1	BeSafe iZi Go handle bar complete	P2003210	7.2.3.03.a	Retailer
2	BeSafe iZi Go upper EPS service kit	901505	7.2.3.03.b	Retailer
3	BeSafe iZi Go lower EPS service kit	J2000835	7.2.3.03.h	Retailer
4	BeSafe iZi Go harness belt w/o crotchstrap	Q2002653	7.2.3.03.c	Distributor/importer
5	BeSafe iZi Go central adjuster service kit	901506	7.2.3.03.e	Retailer
6	BeSafe iZi Go Sun canopy frame with velcro	L2001102	7.2.3.03.f	Retailer
7	BeSafe iZi Go sun canopy spring and screw kit	901502	7.2.3.03.j	Retailer
8	BeSafe iZi Go release handle height adjuster	L2001100	7.2.3.03.g	Retailer
	BeSafe iZi Go sun canopy fabric (black)	553625	7.2.3.03.f (step 1-8)	Consumer
	BeSafe iZi Go fabric	5535XX (xx=colour)	7.2.3.03.i	Consumer


When the seat has been in an (car) accident, the seat must be destroyed.

In that case the retailer must make sure the seat is destroyed and provide the model and serial number to HTS BeSafe AS.

In the case a seat has been in a car accident but is not destroyed, all further responsibility and guarantee of HTS BeSafe AS will be rejected.

Consumer is **ONLY** allowed to replace the fabric (no fabric numbers on this service parts drawing).

The crotch strap is not replaceable!



Form Tolerances Acc. to ISO 2768-K	General Roughness Acc. to NEN 3634	Angular Tolerances Acc. to ISO 2768-M	Scale: 1:10	Units: mm	Mass: 11126g ₂₀	315	500	±2.5
Material:	Treatment:	Engineer: evdv	Checked By:	Date: 5/5/2010		160	315	±1.6
Name: B804 iZi Go X1 Seat assembly						90	160	±0.8
						40	90	±0.45
						10	40	±0.3
						0	10	±0.2
						Linear Tolerances		
Sheet: 1 of 1						From	To	Tol.
Itemnr:	BeSafe®				Drawing Number: B804_8100	Rev.: E	A4	