



Fast Track Repair Service

13817 Fount Beattie Ct., Centreville, VA 20121

(703) 899-5615 | info@fasttrackdmv.org

DRAFT INVOICE

INV-004218

Jul 20, 2026

DRAFT - CUSTOMER AUTHORIZATION NOT SIGNED / COMPLETION ACKNOWLEDGMENT NOT SIGNED

This preview shows the current bill. It is not a finalized signed record and cannot be emailed as the final invoice.

BILL TO

Jordan Taylor

421 Maple Ridge Drive
Suite 204
Ashburn, VA 20147
(703) 555-0148
jordan.taylor@example.com

SERVICE LOCATION

421 Maple Ridge Drive, Suite 204, Ashburn, VA 20147

Upstairs cooling system diagnosis and approved repair.

ISSUE DATE	SERVICE DATE	FIELD RECORD	PAYMENT
Jul 20, 2026	Jul 20, 2026	Authorization And Completion Not Signed	Unpaid

NATURE OF SERVICE REQUEST

Upstairs cooling system diagnosis and approved repair.

SERVICE DETAILS

Approved work

\$354.04

DESCRIPTION	QTY	RATE	AMOUNT
Diagnostic visit and complete HVAC system evaluation	1	\$89.00	\$89.00
45/5 MFD dual-run capacitor replacement	1	\$245.00	\$245.00

WORK SUMMARY & NOTES

Diagnostic completed and approved capacitor replacement installed.

Job cost	\$245.00
Service call	\$89.00
Subtotal	\$334.00
Tax (6.00%)	\$20.04
Total	\$354.04
Deposit / paid	\$0.00
BALANCE DUE	\$354.04

PAYMENT STATUS: UNPAID

Reference INV-004218 with payment. Cash, check, or electronic payment may be recorded separately. Card details are never collected on this document.

FIELD AUTHORIZATION RECORD

AUTHORIZATION OF REPAIR

Customer authorization has not been signed. This draft is for review only and does not record approval to begin work.

Signature not saved

Pending

No field timestamp

COMPLETION OF WORK

Customer completion acknowledgment has not been signed. This draft does not record acceptance of completed work.

Signature not saved

Pending

No field timestamp

Thank you for choosing Fast Track.

Questions? Call (703) 899-5615 or email info@fasttrackdmv.org.