



Fast Track Repair Service

13817 Fount Beattie Ct., Centreville, VA 20121

(703) 899-5615 | info@fasttrackdmv.org

INVOICE

INV-004218

BILL TO

Jordan Taylor

421 Maple Ridge Drive

Suite 204

Ashburn, VA 20147

(703) 555-0148

jordan.taylor@example.com

SERVICE LOCATION

421 Maple Ridge Drive, Suite 204, Ashburn, VA 20147

Upstairs cooling system diagnosis and approved repair.

ISSUE DATE	SERVICE DATE	INVOICE STATUS	PAYMENT
Jul 20, 2026	Jul 20, 2026	Draft	Unpaid

SERVICE DETAILS

Approved work

\$454.74

DESCRIPTION	QTY	RATE	AMOUNT
Diagnostic visit and complete HVAC system evaluation	1	\$89.00	\$89.00
45/5 MFD dual-run capacitor replacement	1	\$245.00	\$245.00
System performance test and operating-temperature verification	1	\$95.00	\$95.00

WORK SUMMARY & NOTES

Replaced the failed dual-run capacitor, verified compressor amperage, and tested a full cooling cycle.

Subtotal	\$429.00
Tax (6.00%)	\$25.74
Total	\$454.74
Paid	\$0.00
BALANCE DUE	\$454.74

PAYMENT STATUS: UNPAID

Reference INV-004218 with payment. Card details are never collected on this document.

REVIEW & APPROVAL

The signer confirms that the listed work and charges were reviewed and approved. The signature is linked to this invoice and retained with an audit timestamp.

Customer approval

Jordan Taylor

Customer | Jul 20, 2026, 12:22 PM

Thank you for choosing Fast Track.

Questions? Call (703) 899-5615 or email info@fasttrackdmv.org.