



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 / +65 9451 6487 +65 6261 4768 sales@masterscan.com.sg

GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922

www.masterscan.com.sg

ULTRASONIC TESTING REPORT

CLIENT & ADDRESS : SEAGULL PTE LTD NO: 7 TUAS SOUTH STREET 15 SINGAPORE 637078				REPORT NO : MSE/SEAGULL/2528-26-UT-RE-SET08-01				Page : 1 of 3											
OWNER : TECHNIPFMC				MSE/REF/NO. : D2-26-2225				LOCATION : Seagull TLP Yard											
PROJECT NAME : FRACKING LINE (PADFLEX)				PROCEDURE : GF/089/NTU/SS/PNO-500011				Date of Testing : 25.03.2026											
PROJECT NO : 00-2528-26				ACCEPTANCE CRITERIA : AWS D1.1, Table 6.3				MATERIAL : CARBON STEEL											
ITEM DESCRIPTION : FABRICATION OF REEL- SET 08								THICKNESS : 8.0 MM											
REQUEST NO : 2528-26-REE-UT-SET08-01																			
WELDING PROCESS : FCAW								STATUS OF WELD : ORIGINAL											
WELD TYPE : COMPLETE JOINT PENETRATION								SURFACE CONDITION : Weld and Clean											
COUPLANT USED : Paper Paste (water based)								POST CLEANING METHOD : Wiping With Cloth											
FLAW DETECTOR / SERIAL NO : USM 36 / 20050040								SURFACE TEMPERATURE : Ambient temperature											
PROBES USED					SENSITIVITY (dB)					TEST RANGE (mm)									
SIZE	ANGLE	FREQ	TYPE	Serial No.	PRIMARY*	SCAN + TR	FINAL												
Ø 24mm	0°	2 MHz	SINGLE	23716	49	6	55	0 ~ 70											
8 x 9 mm	70°	2 MHz	SINGLE	17667	51	14	65	0 ~ 100											
8 X 9mm	70°	4 MHz	SINGLE	93601	48	14	62	0 ~ 100											
*Pre-set At 50% of CRT Full screen height (FSH) using Ø1.5mm SDH calibration block.																			
METHOD OF TESTING : Pulse Echo , A - Scan Contact Method								SENSITIVITY : Ø 1.5mm SDH											
CALIBRATION BLOCK : IIW (V1) Block (MSE-10), V2 Block (MSE-42)																			
SEARCH UNIT CABLE USED TYPE & LENGTH : Lemo To Mini Lemo & 2 Mtr																			
UT SCANNING WAS PERFORMED ON COMPLETE JOINT PENETRATION AREA ONLY.																			
S/N	JOINT NO	THK (mm)	WELDER NO	WELDING PROCESS	INDICATION NO.	TRANSDUCER ANGLE	FROM FACE	LEG I OR II	DECIBELS(dB)				DISCONTINUITY				CLASS	RESULTS	REMARKS
									#	IN	DI	RE	FE	AT	TE	NU			
									a	b	c	d							
DISCONTINUITY : CLASS - A, CLASS - B, CLASS - C, CLASS - D																			
For more details please refer to the attached photograph sheet																			
Tested by : J.JANAGAR PCN NDT LEVEL II				Reviewed By : SURENDRAKUMAR P.V ASNT NDT Level III				Reviewed By :				Reviewed By :							
SIGNATURE				SIGNATURE															
DATE : 25.03.2026				DATE : 26.03.2026				DATE :				DATE :							

FORM NO : MSE/NDT/UT/001 Rev.1a

The report is issued under the following terms and conditions:

- The report shall not be reproduced in part or in full unless approved in writing has been given by MASTERSCAN.
- MASTERSCAN shall not be used in any way, directly or indirectly, for the purpose of liability in the manner of performing the tests, inspections or services but no warrants are given, and none may be implied directly or indirectly relating to MASTERSCAN.
- MASTERSCAN shall not be held responsible for any damage or loss of property or equipment caused by the use of the report.
- MASTERSCAN shall not be held responsible for any damage or loss of property or equipment caused by the use of the report.
- MASTERSCAN shall not be held responsible for any damage or loss of property or equipment caused by the use of the report.
- The test report is prepared based on the test(s) requested and on the specific items submitted / sampled to MASTERSCAN for testing. MASTERSCAN assumes no responsibility for variations in quality or other characteristics of product produced on supplied under conditions over which MASTERSCAN has no control. MASTERSCAN Engineering' testing does not constitute a recommendation for, or endorsement of the product or material tested.



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 / +65 9451 6487 +65 6261 4768 sales@masterscan.com.sg
GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922
www.masterscan.com.sg

ULTRASONIC TESTING REPORT

REPORT NO : MSE/SEAGULL/2528-26-UT-RE-SET08-01

PAGE : 2 OF 3

S/N	JOINT NO	THK mm	WELDER NO.		WELDING PROCESS	WPS NO	WELD TYPE	MAT'L	Distance from Reference Point (mm)	Type of indication	RESULT	REMARKS
			ROOT	CAPPING								
DRAWING NO : IREE-00042029-001 Rev 1												
1	31	8.0	SGMO-ST-037		FCAW	SGM-WPS-23-07	CJP	CS	-	-	ACCEPTABLE	
2	32	8.0	SGMO-ST-037		FCAW	SGM-WPS-23-07	CJP	CS	-	-	ACCEPTABLE	

Tested and Reported By :
J.JANAGAR
PCN NDT Level II



DATE : 25.03.2026

Reviewed By :
SURENDRAKUMAR P.V
ASNT NDT Level III



DATE : 26.03.2026

Reviewed By :

DATE :

Reviewed by :

DATE :



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 / +65 9451 6487 +65 6261 4768 sales@masterscan.com.sg
GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922
www.masterscan.com.sg

ULTRASONIC TESTING REPORT

REPORT NO : MSE/SEAGULL/2528-26-UT-RE-SET08-01

PAGE : 3 OF 3

