

ABC GENERAL INSURANCE LTD.
FNOL Registration Form

FNOL Date	28-May-2026
FNOL Registration Number	FNOL-2026-0003
Member ID	MEM-1003
Policy Number	POL-2024-003
Vehicle Registration Number	DL01EF2234
Vehicle Make	Hyundai
Vehicle Model	Creta
Vehicle Year	2020
Incident Date and Time	27-May-2026 22:15
Incident Type	THEFT_COMPLETE
Incident Location	Basement Parking — Green Avenue Apartments, Sector 21, Dwarka, New Delhi – 110075
Damage Description	The insured vehicle (Hyundai Creta, DL01EF2234) was parked in the basement parking of the claimant's residential complex overnight. On the morning of 28-May-2026, the claimant discovered that the vehicle was missing from its designated parking bay (Bay No. B-14). The claimant has searched the premises and confirmed the vehicle is not on the property. CCTV footage from the complex is being reviewed by the Dwarka police. All three sets of keys are with the claimant.
Third-Party Involved	No
Third-Party Injury Reported	No
FIR Filed	Yes
FIR Number	DL-DWK-2026-1847
Police Station	Dwarka Sector 21 Police Station, New Delhi
Legal Notice or Tribunal Ref.	No
Claim Type Preferred	Reimbursement
Preferred Garage	Not applicable — theft claim
Adjuster ID	ADJ-103

Declaration: I confirm that the information provided above is true and correct to the best of my knowledge. I understand that any misrepresentation may result in the rejection of this claim.

Claimant signature: _____ Date: _____

GOVERNMENT OF INDIA — MINISTRY OF ROAD TRANSPORT AND HIGHWAYS

REGISTRATION CERTIFICATE (SMART CARD FORMAT)

Issued by: Regional Transport Office, Delhi West (DL-01)

Registration Number	DL01EF2234
Registration Date	12-Nov-2020
Owner Name	[Masked — MEM-1003]
Address	[Masked — Dwarka, New Delhi]
Vehicle Class	Motor Car (LMV — Light Motor Vehicle)
Make	Hyundai Motor India Ltd.
Model	Creta SX (O) 1.5 Petrol
Body Type	Sport Utility Vehicle
Fuel Type	Petrol
Engine Displacement	1497 cc
Number of Cylinders	4
Seating Capacity	5 (including driver)
Unladen Weight	1340 kg
Engine Number	G4FD8765432
Chassis Number	MALC241CLMM987654
Colour	Typhoon Silver
RTO	DL-01 (Delhi West)
Registration Valid Upto	11-Nov-2035
Fitness Valid Upto	11-Nov-2025
Insurance Policy No.	POL-2024-003
Insurance Valid Upto	30-Apr-2025
Hypothecation	ICICI Bank Limited, Connaught Place, New Delhi — Charge registered
PUC Valid Upto	09-Oct-2026
National Permit	Not applicable

Issued by Registering Authority, DL-01. This is a digitally signed document. Verify at <https://parivahan.gov.in>.

DELHI POLICE — FIRST INFORMATION REPORT
Under Section 154 Cr.P.C.

FIR Number	DL-DWK-2026-1847
Police Station	Dwarka Sector 21 Police Station
District	South West Delhi
State	Delhi
Date of FIR	28-May-2026
Time of FIR	09:45 hrs
Date of Incident	27-May-2026 (reported following morning)
Time of Incident	Estimated 22:15 hrs — 02:00 hrs (overnight theft)
Place of Incident	Basement Parking, Green Avenue Apartments, Sector 21, Dwarka, New Delhi — 110075

COMPLAINANT DETAILS

Name	[Masked — MEM-1003]
Address	[Masked — Sector 21, Dwarka, New Delhi]
Phone	[Masked]
Vehicle Reg.	DL01EF2234 (Hyundai Creta SX (O), 2020)

INCIDENT DESCRIPTION

The complainant states that on the night of 27-May-2026, the insured vehicle (Hyundai Creta, DL01EF2234) was parked in designated Bay No. B-14 in the basement parking of Green Avenue Apartments, Sector 21, Dwarka. On the morning of 28-May-2026 at approximately 06:30 hrs, the complainant discovered that the vehicle was missing from the parking bay. The complainant searched the entire parking facility and confirmed that the vehicle was not on the premises. The complainant approached the residential welfare association and requested review of CCTV footage. Preliminary review of CCTV cameras indicates that the vehicle was driven out of the basement at approximately 02:15 hrs on 28-May-2026. The footage is being preserved and will be shared with the investigating officer. All three sets of vehicle keys are in the possession of the complainant. The vehicle loan from ICICI Bank is active.

Third-Party Vehicle	Not applicable — theft case
Injuries	None
Vehicle Keys Status	All 3 sets in complainant's possession
CCTV Evidence	Footage available — being preserved for investigation
Sections Invoked	IPC Section 379 (theft); IPC Section 411 (dishonestly receiving stolen property)
FIR Status	Registered — vehicle theft
Investigating Officer	Sub-Inspector, Dwarka Sector 21 PS [Badge on file]

Signature of Officer: _____ Stamp: _____

This is a computer-generated FIR copy. Valid without physical signature as per Delhi Police Digital Records Act.

VEHICLE DAMAGE PHOTOGRAPH LOG

FNOL-2026-0003 · DL01EF2234 (Hyundai Creta 2020) · 28-May-2026

Photographs captured at scene by adjuster ADJ-103 using authorised mobile application.

This log is the photographic evidence record for this claim. Each entry records the filename, timestamp, GPS location, view angle, and damage observed.

#	Filename	Timestamp	GPS	View	Observation
1	IMG_20260528_064512	28-May-2026 06:45	28.5941° N, 77.0537° E	Parking bay B-14 — full view	Designated parking bay B-14 is empty. Bay marking and bay number clearly visible. No debris or signs of forced entry to bay gate.
2	IMG_20260528_064531	28-May-2026 06:45	28.5941° N, 77.0537° E	Parking bay — entry ramp	Basement entry ramp and security barrier visible. Barrier is intact. No tyre marks or damage to barrier.
3	IMG_20260528_064558	28-May-2026 06:46	28.5941° N, 77.0537° E	CCTV camera — coverage angle	CCTV camera position documented. Camera covers Bay B-14 and the access lane. Footage confirmed available with security office.
4	IMG_20260528_064620	28-May-2026 06:46	28.5941° N, 77.0537° E	CCTV still — vehicle exit	Printed still from CCTV footage at 02:15 hrs on 28-May-2026 showing a vehicle consistent with a Hyundai Creta being driven out of the basement access lane. Footage retained by police.
Total photographs		4			
Photo quality		Clear — morning light and artificial parking illumination			
Vehicle condition at time		Vehicle absent — theft confirmed by empty bay and CCTV			
Key surrender status		All 3 sets of keys confirmed in complainant's possession at time of inspection. Key surrender to be arranged as per insurer's theft claim procedure.			
Adjuster observation		Parking bay is empty and consistent with vehicle theft. No signs of accident or collision damage in the bay. CCTV evidence is available and has been noted. Vehicle hypothecated to ICICI Bank — NOC from financier will be required before claim can be processed. Key surrender confirmation required.			