# ROADSENSE | Infrastructure Intelligence

**DATE:** November 08, 2026
**STANDARD:** ASTM D6433 / IRI

| ASTM D6433 CONDITION | ROUGHNESS INDEX (IRI) | MATERIAL REQUIRED | ESTIMATED REPAIR BUDGET |
|---|---|---|---|
| **10.0 / 100**<br>**Serious / Failed** | **7.72** m/km<br>ASTM E1926 | **183.5 kg**<br>Cold-Mix Bitumen | **Rs. 16392**<br>($431.68) |

## Hazard Classification & Severity Breakdown

| Hazard Category | Impact Severity | Count | Recommended Municipal Action |
|---|---|---|---|
| Pothole | Severe (Z >= 3.0) | 18 | Immediate Cold Patching / Asphalt Mill & Infill (<48h) |
| Pothole | Moderate (Z 2.0-3.0) | 7 | Scheduled Maintenance (<14 days) |
| Pothole | Minor / Anomaly (Z < 2.0) | 2 | Surface Seal Coating / Monitor |
| Speedbreaker | Standard Deflection | 0 | Verify Regulatory Height & Signage Painting |

## Priority Maintenance Dispatch Table (Top Critical Hazards)

| ID | Type | Severity | Latitude | Longitude | Dimensions | Bitumen Mass | Est. Budget | Action |
|---|---|---|---|---|---|---|---|---|
| #01 | Pothole | Low | 12.919232 | 77.554691 | 150cm² x 2.5cm | 0.5 kg | Rs.350 | Routine Repair |
| #02 | Pothole | Severe | 12.919191 | 77.554664 | 5107cm² x 2.5cm | 15.0 kg | Rs.975 | Emergency Patch |
| #03 | Pothole | Severe | 12.919157 | 77.554647 | 5107cm² x 2.5cm | 15.0 kg | Rs.975 | Emergency Patch |
| #04 | Pothole | Severe | 12.918762 | 77.554504 | 1750cm² x 2.5cm | 5.2 kg | Rs.532 | Emergency Patch |
| #05 | Pothole | Severe | 12.918739 | 77.554518 | 1750cm² x 2.5cm | 5.2 kg | Rs.532 | Emergency Patch |
| #06 | Pothole | Severe | 12.918629 | 77.554462 | 2436cm² x 2.5cm | 7.1 kg | Rs.621 | Emergency Patch |
| #07 | Pothole | Moderate | 12.918526 | 77.554440 | 805cm² x 2.5cm | 2.4 kg | Rs.407 | Routine Repair |
| #08 | Pothole | Severe | 12.918417 | 77.554392 | 2086cm² x 2.5cm | 6.1 kg | Rs.576 | Emergency Patch |
| #09 | Pothole | Severe | 12.918392 | 77.554381 | 2086cm² x 2.5cm | 6.1 kg | Rs.576 | Emergency Patch |
| #10 | Pothole | Severe | 12.918209 | 77.554354 | 3644cm² x 2.5cm | 10.7 kg | Rs.781 | Emergency Patch |
| #11 | Pothole | Severe | 12.917763 | 77.554319 | 1684cm² x 2.5cm | 4.9 kg | Rs.522 | Emergency Patch |
| #12 | Pothole | Severe | 12.917735 | 77.554322 | 1684cm² x 2.5cm | 4.9 kg | Rs.522 | Emergency Patch |

## Camera Ground-Truth Evidence (AI Detection Bounding Boxes)

Visual verification frames captured by vehicle optical sensors at timestamp of impact.










