

Release Note N°: RN230926058E



Page N°: 1/ 3

BOSS NO- 500006012
Report Ref No.- KOL/JSS/12A/2023

RELEASE NOTE

DATE: 26.09.2023

Name of The Project : Augmentation of ground water based piped water supply scheme for Dakshin Bhebia Zone-II to accommodate FHTC

Name of The Division : Barasat Division
Office of the Executive Engineer,
Resources Division Public Health Engineering Dte, West

Name of The Client : Bengal, Janaswasthya Karigari Bhawan (Nijalaya),
C N B Street No-18, CN Block, Sector-V,
Bidhannagar, Kolkata- 700091.

Name and Address of Vendor/
Manufacture : M/s. Rashmi Metaliks Ltd. ,
Gokulpur, P.O-Shyamraipur, Kharagpur,
Dist: West Midnapur, West Bengal.

Client's Letter Ref. No. & Date : Memo No. 2628/RS Dated:25.08.2023

Inspection call reference : SO/2000004995 Date: 28.08.2023

Date (s) & Place (s) of inspection : At the works of M/s. Rashmi Metaliks Limited, on 28.08.2023,
29.08.2023, 30.08.2023, 31.08.2023, 01.09.2023, 02.09.2023
& 03.09.2023

Details of Material offered & inspected as per the PO referred above are as under

Item No. As Per PO	Item No. as per Contract / Order Brief Description of the Item	Quantity As per contract / order (Mtrs.)	Quantity Previously Passed (Mtrs.)	Quantity Offered (Mtrs.)	Quantity Now Passed (Mtrs.)	Quantity Rejected (Mtrs.)	Quantity Balance (Mtrs.)
Details as per Annexure							



SGS India Private Ltd

Ecospace, Block – 3 A, 2nd Floor, East Wing, Premises
IIF/11, Action Area – II, Rajarhat, New Town,
Kolkata - 700 156
Phone: +91 33 665 06 100 - 101 (B)
Fax: +91 33 232 40 745

This document is issued by the Company subject to its General Conditions of Service (<http://www.sgs.com/en/Terms-and-Conditions.aspx>). Attention is drawn to the limitation of liability, indemnification and jurisdictional issues established therein. This document is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The authenticity of this document may be verified at <https://sgsonsite.sgs.com/en/v2/common/ecertificate/authenticateCertificate.jsp>.

Release Note N°: RN230926058E



Page N°: 2/ 3

BOSS NO- 500006012
Report Ref No.- KOL/JSS/12A/2023

RELEASE NOTE

DATE: 26.09.2023

Reference Document No. (Spec.../ Standard / Code / Drawing / Sampling Standard / Any Other)	Scope of Inspection (Checks/Tests- witnessed & reviewed)	W	R	Observations / Results
Client's Letter Ref. No. & Date: Memo No. 2628/RS Dated:25.08.2023 QAP / ITP No : QAP No.: RML/DIP/QAP/001 Dated: 03.08.2023 Revision: Nil (Manufacture's provided QAP) Approved Drawing No. : N/A Reference standard / code / specification & Edition / Version / Year : IS 8329 : 2000 (For D.I. Pipes) IS 5382 : 2018 (For Rubber Gaskets) Sampling Standard & Edition / Version / Year : As per approved QAP	For Pipes (1) Visual examination for workmanship and finish. (2) Dimensional Check (3) Mechanical Test (4) Hydrostatic Pressure Test. (5) Black Bitumen Coating Thickness Check (6) Cement lining Thickness check (7) Zinc- Coating Thickness (8) Verification of Quantity (9) Verification of Marking. (10) Manufacturer Internal test reports For Rubber Gaskets (11) Review of Rubber Gasket Test Certificate	☒ ☒ ☒ ☐ ☒ ☐ ☐ ☒ ☒ ☐ ☐	☐ ☐ ☐ ☒ ☐ ☐ ☒ ☐ ☐ ☒ ☒	Satisfactory.

Marking on Pipes: : Body: IS 8329, RASHMI AQUA, ISI Logo, CML NO. 5533060.

Socket: Class, Batch no, Size, Length, DI, Year, IND

Spigot: Size, Length, Insertion Mark

Conclusion : This is Final Inspection Report. The inspected quantity is passed.

Remarks : Inspection requested by Manufacturer for the scope, sampling plan as agreed and attended.

Deviation accepted (if any) : NIL

Inspection Identification	Location of Identification	Inspected By	Signature of SGS Representative
SGS Hologram sticker' double affixed on sample pipes and single on rest of the pipes.	On the Socket Face	N DEY / I.KARAK / S. NANDI/J.S.SAHOO / A.ROY / D BANDYOPADHYAY / S.ROY	

This inspection has been carried out to the best of our knowledge & our responsibility is limited to the exercise of reasonable care. This Release Note reflects our findings at the time & place of inspection and is This inspection not intended to relieve the seller from their contractual obligations.

"In accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgsgroup.in/Service-Terms>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the company's findings at the time of it's intervention only and within the limits of client's instructions, if any. The company's sole responsibility is to its client and this document(s) does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

"The information stated in the Release Note is derived from the results of inspection or testing procedures carried out in accordance with the instruction of our clients and / or our assessment of such results on the basis of any technical standards, trade custom or practice, or other circumstances which should in our professional opinion be taken into account



SGS India Private Ltd

Ecospace, Block – 3 A, 2nd Floor, East Wing, Premises
IIF/11, Action Area – II, Rajarhat, New Town,
Kolkata - 700 156
Phone: +91 33 665 06 100 - 101 (B)
Fax: +91 33 232 40 745

This document is issued by the Company subject to its General Conditions of Service (<http://www.sgsgroup.in/Service-Terms>). Attention is drawn to the limitation of liability, indemnification and jurisdictional issues established therein. This document is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The authenticity of this document may be verified at <https://sgsonsite.sgsgroup.in/v2/common/ecertificate/authenticateCertificate.jsp>.

ANNEXURE

BOSS NO- 500006012
Report Ref No.- KOL/JSS/12A/2023

RELEASE NOTE

DATE: 26.09.2023

Item # as per Contract/ Order	Description & Size	Quantity as per Contract / Order (Mtrs.)	Quantity Previous ly passed (Mtrs.)	Quantity Offered (Mtrs.)	Quantity Now Passed (Mtrs.)	Quantity Rejected (Mtrs.)	Quantity Balance (Mtrs.)
	Centrifugally cast (Spun) Ductile Iron Pipes with spigot & Socket end, with internally cement mortar lining and externally zinc coated & finally Black Bitumen coated as per IS 8329:2000 with latest Amendment.						
90.	Ø150mm (K-7) = 5.5Mtrs x 291 Pcs. Batch No.: 14H	1,600.5	0.0	1,600.5	1,600.5	0.0	0.0
	RUBBER GASKETS:						
	Ø150 mm EPDM (Tyton)						
	Make & Batch No.: MRI : 180623 to 300623	-----	-----	306 Pcs.	306 Pcs.	-----	-----

For SGS India Private Ltd

This inspection has been carried out to the best of our knowledge & our responsibility is limited to the exercise of reasonable care. This Release Note reflects our findings at the time & place of inspection and is This inspection not intended to relieve the seller from their contractual obligations.

"In accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgsgroup.in/Service-Terms>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the company's findings at the time of its intervention only and within the limits of client's instructions, if any. The company's sole responsibility is to its client and this document(s) does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

"The information stated in the Release Note is derived from the results of inspection or testing procedures carried out in accordance with the instruction of our clients and / or our assessment of such results on the basis of any technical standards, trade custom or practice, or other circumstances which should in our professional opinion be taken into account".

SGS

SGS India Private Ltd

Ecospace, Block – 3 A, 2nd Floor, East Wing, Premises
IIF/11, Action Area – II, Rajarhat, New Town,
Kolkata - 700 156
Phone: +91 33 665 06 100 - 101 (B)
Fax: +91 33 232 40 745

This document is issued by the Company subject to its General Conditions of Service (<http://www.sgs.com/en/Terms-and-Conditions.aspx>). Attention is drawn to the limitation of liability, indemnification and jurisdictional issues established therein. This document is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The authenticity of this document may be verified at <https://sgsonsite.sgs.com/en/v2/common/ecertificate/authenticateCertificate.jsp>.