

ROAD DAMAGE INSPECTION REPORT

User: salina

Inspection Date: 2026-06-06T16:19:52.904539

Location: , ,

Road Name:

GPS: /

File Name: image_20260606_161951_WhatsApp Image 2026-06-06 at 3.18.17 PM.jpeg

Total Potholes	2
Total Cracks	0
Critical Damages	2
Condition Score	10%

Recommendations

- Emergency repair required for critical damage zones.
- Pothole repair recommended on affected road sections.
- Immediate road maintenance required due to low condition score.