

ROAD DAMAGE INSPECTION REPORT

User: salina

Inspection Date: 2026-06-06T23:18:38.957378

Location: , ,

Road Name:

GPS: /

File Name: image_20260606_231838_WhatsApp Image 2026-06-06 at 3.18.17 PM.jpeg

Total Potholes	0
Total Cracks	0
Critical Damages	0
Condition Score	100%

Recommendations

- No immediate structural maintenance recommended. Continue monitoring.