

ROAD DAMAGE INSPECTION REPORT

User: App Test User

Inspection Date: 2026-06-06T15:45:44.680212

Location: SampleCity, SampleState, SampleLand

Road Name: Sample Road

GPS: 12.3456 / 65.4321

File Name: sample_2.gif

Total Potholes	2
Total Cracks	0
Critical Damages	1
Condition Score	40%

Recommendations

- Emergency repair required for critical damage zones.
- Pothole repair recommended on affected road sections.