



|                   |                       |                           |
|-------------------|-----------------------|---------------------------|
| Tugela 3<br>SITE  | Wetland<br>TYPE       | 9.9 ha<br>AREA            |
| WARNING<br>STATUS | 86.0%<br>FIELD HEALTH | 28.5%<br>SATELLITE HEALTH |

SITE LOCATION




CURRENT NDVI



Observation: 2025-12-26 | Latest monthly NDVI: 0.1641

NDVI HISTORY



DECISION SUMMARY

Trend: Stable • Status: WARNING • Outlook: Monitor closely  
Recommendation: Monitor closely and prioritise routine restoration follow-up.