JSX

7201 Lemmon Ave., ATTN: JSX PARTS
Dallas, TX, US, 75209

N949JX
EMB-145LR
SN 145639

Work Order / Plan No. SLC MX-706
Service Center Elevate MRO

9JX-241007-552 **A/F (145639)**

Task: Discrepancy Req: AOG

AOG

Requirement	Due
Mos	[07-Oct-2024]
Hrs	
Ldg	

Putting the LG down, received LG AIR/GND FAIL message. Ran through QRH, upon go around LG would not come up. Got vectored around and came in and landed. Message went away after touching down.

32-00 - Snag

(Date reported: 07-Oct-2024), (Reported by: Price, Zach, Title: Pilot), (Event category: En Route), (Reported severity: AOG) (Classification date: 07-Oct-2024), (Recorded by: King, Timothy, Title: CAMO), (Operational restrictions:)

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

Compliance A/F (145639)	Mos	07/OCT/2024	Hrs	42,880.08	Ldg	33,759	Other	

Action Taken: After inspection of L/H gear FWD "Down Lock Sensor" found loose connector. Cleaned + tightened connector in reference to Embraer 145 MM Chapter 20-50-00 SWPM

Cost:

Man Hrs.: 2.0

Component Description	P/N OFF	S/N OFF
	P/N ON	S/N ON

Component Description	P/N OFF	S/N OFF
	P/N ON	S/N ON

Technician Name: Nathan Acuna

License: CRS#K5SR339N
Signature:

Inspector Name: Sam Perez

License: FAA CRS K5SR339N
Signature: