# DAS MATERIAL TESTINGS PVT LTD

Estd : 1991

28, Velachery Road, Little Mount, Saidapet, Chennai - 600 015
Phone: 044 - 22334253, 22300163, 22300563, 9841033962
Email: dasmaterial@yahoo.com Web: www.dasmaterial.in


## TEST REPORT



**Report No.** : **6031101**
**Date** : 16.03.2026

Customer:
Mr. Kanith Kumar,
Red Rox Industries Pvt. Ltd.,
Chennai – 600 042.

Customer's Reference : Letter Dated: 11.03.2026
Sample Received : 11.03.2026
**Project /Name of work* : -
**Sample Description* : *Interlocking Bricks, 5nos*
*Brand: Red Rox Industries*
*Size: 300 x 150 x 95mm*

## COUNTRY BRICKS – COMPRESSIVE STRENGTH TEST

| S. No. | Sample Details | | Breaking Load (kN) | Compressive Strength ($N/mm^2$) |
|---|---|---|---|---|
| | **Sample ID* | Weight (kg) | | |
| 1. | - | 8.870 | 521 | 11.58 |
| 2. | - | 8.705 | 564 | 12.53 |
| 3. | - | 8.750 | 531 | 11.80 |
| 4. | - | 8.460 | 567 | 12.60 |
| 5. | - | 8.710 | 522 | 11.60 |
| | | | Average | 12.02 |

Test Conducted as per IS 3495(Part 1): 2019
Test Result Conforms as per IS 1077: 2025(Class: 10)

Remarks:
**As furnished by the customer*
Sample submitted by the customer

-End of Report

For DAS MATERIAL TESTINGS PVT LTD.

Brenno Damian, B.E., M.S.
Managing Director

For more information on our product sales and testing services, refer overleaf...


Note: This report relates only to the particular sample(s) inspected and is valid for atomed sight such that this certificate • Sample will be destroyed after days from the date of receipt of ermatts or unless instructed otherwise • Any complaints about this report should be communicated within days. It is not the report • This report should be reproduced exactly in full and cannot be used as an evidence to a dispute that not be used in that testing media without permission in writing • Sample description is not provided in all tasks and is given as described by the customer • Samples are not drawn by us unless specified • Laboratory is not responsible for the authenticity of the photocopied test reports.

# DAS MATERIAL TESTINGS PVT LTD

Estd : 1991

28, Velachery Road, Little Mount, Saidapet, Chennai - 600 015
Phone: 044 - 22354253, 22300163, 22300563, 9841033962
Email: dasmaterial@yahoo.com Web: www.dasmaterial.in


## TEST REPORT



**Report No.** : **6031101**
Date : 16.03.2026

Customer:
Mr. Kanith Kumar,
Red Rox Industries Pvt. Ltd.,
Chennai – 600 042.

Customer's Reference : Letter Dated: 11.03.2026
Sample Received : 11.03.2026
**Project /Name of work* : -
**Sample Description* : *Interlocking Bricks, 5nos*
*Brand: Red Rox Industries*
*Size: 300 x 150 x 95mm*

## COUNTRY BRICKS – WATER ABSORPTION TEST

| S. No | **Sample ID* | % of water Absorption (%) |
|---|---|---|
| 1. | - | 8.41 |
| 2. | - | 7.23 |
| 3. | - | 7.51 |
| 4. | - | 7.46 |
| 5. | - | 6.93 |
| | Average | 7.51 |

Limits: Max 20%
Test Conducted as per IS 3495(Part 2): 2019.
Test Result Conforms as per IS 1077: 2025.

Remarks:
**As furnished by the customer*
Sample submitted by the customer

-End of Report

For DAS MATERIAL TESTINGS PVT. LTD.

*Brenno Damian, B.E., M.S.*
*Managing Director*


For more information on our product sales and testing services, refer overleaf...

**Note:** This report relates only to the particular sample(s) submitted for test • Any correction not attested shall invalidate this certificate • Sample will be destroyed after 15 days from the date of issue of certificate unless instructed otherwise • Any complaints about this report should be communicated in writing within 7 days of this report • This report should not be reproduced except in full and cannot be used as an evidence in a court of law and shall not be used in advertising media without prior permission in writing • Sample descriptions is not verified in all cases and is given as described by the customer • Samples are not drawn by us unless otherwise stated • Laboratory is not responsible for the authenticity of the photocopied test reports.