Fabric Defect Inspection Report

Company Name:	Noao	**Date:**	2026-08-08 09:49:14
Operator Name:	knwfin	**Inspection ID:**	INSP-2F5E242E
Roll ID:	455	**Batch ID:**	789
Fabric Type:	Cotton	**Final Verdict:**	PASS

Inspection Image:

Quality Score: 96.5/100

Detected Defects:

Type	Confidence	Dimensions (cm)	Area (cm2)	Severity	Suggestion
person	0.29	3.58 x 2.98	10.66	Minor	Inspect Manually