



ಕರ್ನಾಟಕ ಸರ್ಕಾರ

ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ, ಮೇಲೂರು ಶಿಡ್ಲಘಟ್ಟ ತಾಲ್ಲೂಕು, ಚಿಕ್ಕಬಳ್ಳಾಪುರ (ಜಿಲ್ಲೆ)

Date: 2/07/2026.

Lab Report

water Sample test Report

Source of water:

Borewell water

Village name:

Grd Lakshmi School.
Chikkadavahalli.

collection date & time: - 29/06/26

collected at - 10 AM.

Test type: - H2S media

Report / Result: - [portable]

LAB TECHNICAL OFFICER
Primary Health Center
Melur, Sidlaghatta Taluk
Chikkaballapur Dist.

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 02/07/2026

It is certified that an inspection team headed by Devraj B M Medical Officer (Name of Officers with designation) from Primary Health Center Melur Sidlaghatta Taluk Chikkaballapura District (Name of Department/ Office) inspected the **SRI LAKSHMI VIDHYANIKETHANA H P SCHOOL** (Name & Address of the school) on 29/06/2026 (date of inspection) and found that the **SRI LAKSHMI VIDHYANIKETHANA H P SCHOOL** (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of 02 years till 01/07/2028

Signature with Seal:

Name

: Devraj B M

Designation

: Medical Officer

Name & Address of the Office / Department :

Primary Health Center Melur Sidlaghatta Taluk

Chikkaballapura District

To

**SRI LAKSHMI
VIDHYANIKETHANA H P SCHOOL**

Chikkadasarahalli Sidlaghatta

(Name & Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.