TECHNICAL SERVICE & MAINTENANCE REPORT

Machine, technician and reported issue

Report ID	TMR-SAMPLE-FOUR-STEPS
Report generated	29 Oct 2026, 10:39 AM IST
Issue status	Under Investigation

1. Machine Details

Machine / asset ID	Not recorded
Machine name	Horizontal band saw
Machine model	HAB-3232
Machine type	Not recorded

2. Technician Details

Technician name	Not recorded
Technician email	Not recorded
Service date	Not recorded

3. Reported Issue

Issue title	Saw blade vibration

Reported date and time	Not recorded

TECHNICAL SERVICE & MAINTENANCE REPORT

Technician-confirmed work record

4. Troubleshooting & Corrective Actions

Step	Action Taken	Technician Observation	Status
1	Inspect saw blade for broken teeth	Broken teeth detected	Completed
2	Replace damaged saw blade	Not provided	Completed
3	Measure stock dimensions	Not provided	Completed
4	Select correct TPI blade	Not provided	Completed

5. Troubleshooting Summary

Performed steps	4 completed; 0 attempted unsuccessfully
Key findings	Broken teeth detected
Corrective actions recorded	Confirmed actions are listed in Section 4.

TECHNICAL SERVICE & MAINTENANCE REPORT

Final status, remarks and signatures

6. Final Maintenance Status

Reported issue	Saw blade vibration
Issue resolution status	Under Investigation
Machine operational status	Not Recorded
Functional test result	Not tested
Final technician remarks	SAMPLE ONLY: based on the four-step example supplied in the request, not a verified service record.
Return-to-service authorization	Not authorized

7. Recommendations

No follow-up recommendations recorded.

8. Approval & Signatures

Role	Name	Signature	Date
Maintenance Technician			
Maintenance Supervisor / Admin			
Customer Representative			

Report Prepared By: Not recorded

Report Reviewed By: Pending

Approval Status: Pending. Signatures are to be completed by the responsible people.