

INDUSTRIAL BRAIN	Work Order	Doc ID: Work_Order_9981
	Effective: 2023-01-01	Rev: 1.0

Work Order: WO-9981

Status: CLOSED **Created:** 2023-12-04 **Priority:** Emergency **Asset:** Pump P-101

Description: Rebuild Pump P-101 following catastrophic bearing failure.

Actions Taken (John Smith): - Replaced bent shaft. - Installed new inboard and outboard bearings. - Packed with 15g SynthoLube-X9. - Replaced mechanical seals. - Laser aligned to Motor M-22.

Sign-off: J. Smith (2023-12-06)

Prepared By / Technician

Approved By / Supervisor